



**CEBORA S.P.A.**  
Via Andrea Costa, 24  
40057 Cadriano di Granarolo  
Bologna, Italy

Tel: +39 - 051765000  
Fax: +39 - 051765222  
P.IVA 00521371203  
E-mail: [cebora@cebora.it](mailto:cebora@cebora.it)  
Web: <http://www.cebora.it>

---

Document

*Documento*

**Firmware upgrade history**

***Storico aggiornamenti Firmware***

Model

*Modello*

**SYNSTAR 330/TC**

Code

*Articolo*

**8038600**

Firmware version

**21**

*Versione firmware*

Issue date

**29/01/2025**

*Data di rilascio*

---

**ITALIANO.....**.....**2**

**ENGLISH.....**.....**4**

## ITALIANO

### Aggiornamenti Firmware rel. "21"

- Aggiornamenti interni

### Aggiornamenti Firmware rel. "20"

- Aggiunto supporto per torcia push-pull Parker

### Aggiornamenti Firmware rel. "19"

- Aggiornamenti interni

### Aggiornamenti Firmware rel. "18"

- Aggiornamenti interni

### Aggiornamenti Firmware rel. "17"

- Aggiornamenti interni

### Aggiornamenti Firmware rel. "16"

- Aggiornamenti interni

### Aggiornamenti Firmware rel. "15"

- Aggiornamenti interni

### Aggiornamenti Firmware rel. "14"

- Aggiornamenti interni

### Aggiornamenti Firmware rel. "13"

- Aggiunta lingua russa
- Migliorate le partenze con Alluminio

### Aggiornamenti Firmware rel. "12"

- Modifiche interne

### Aggiornamenti Firmware rel. "11"

- Aggiunti programmi sinergici:
  - Fe SG2 0.8mm Ar+8%CO<sub>2</sub> (SHORT, PULSE)
  - Fe SG2 1.0mm Ar+8%CO<sub>2</sub> (SHORT, PULSE)
  - Fe SG2 1.2mm Ar+8%CO<sub>2</sub> (SHORT, PULSE)

### Aggiornamenti Firmware rel. "10"

- Aggiunti programmi sinergici:
  - Rutilo (E71T-1) 1.2mm Ar+18%CO<sub>2</sub> (SHORT)
  - Metal 1.2mm Ar+18%CO<sub>2</sub> (SHORT, PULSE)
  - AlSiCu (4145) 1.2mm 100%Ar (SHORT, PULSE)
  - X96 (ER120-S) 0.8mm Ar+25%CO<sub>2</sub> (SHORT, PULSE)
- Modifiche interne

### Aggiornamenti Firmware rel. "9"

- Modifiche interne

### Aggiornamenti Firmware rel. "8"

- Modifiche interne



## Aggiornamenti Firmware rel. "7"

- Migliorata l'interfaccia grafica
- Modifiche interne

## Aggiornamenti Firmware rel. "6"

- Modificata modalità TIG 3L in accordo con il MIG 3L
- Migliorata l'interfaccia grafica

## Aggiornamenti Firmware rel. "5"

- Migliorata l'interfaccia grafica

## Aggiornamenti Firmware rel. "4"

- Aggiunte curve sinergiche:
  - AlSi12 (4047) 1.0mm 100%Ar (SHORT, PULSE)
  - AlMg2.7Mn (5554) 1.2mm 100%Ar (SHORT, PULSE)
- Aggiunta la possibilità di disabilitare l'anti-stick in MMA
- Aggiunta la selezione delle unità di misura metrico (mm) / imperiale (inches)
- Migliorata l'interfaccia grafica

## Aggiornamenti Firmware rel. "3"

- Aggiunta gestione automatica della retroilluminazione del display
- Aggiunto supporto per torcia art.1245 con up/down

## Aggiornamenti Firmware rel. "2"

- Aggiunta funzione blocco pannello con PIN code opzionale
- Aggiunta visualizzazione misure dallo stato di HOLD
- Aggiunto supporto per controllo qualità e Datalogger art.408



## ENGLISH

### Update firmware release “21”

- Internal improvements

### Update firmware release “20”

- Added support for Parker push-pull torch

### Update firmware release “19”

- Internal improvements

### Update firmware release “18”

- Internal improvements

### Update firmware release “17”

- Internal improvements

### Update firmware release “16”

- Internal improvements

### Update firmware release “15”

- Internal improvements

### Update firmware release “14”

- Internal improvements

### Update firmware release “13”

- Added new language (russian)
- Updates departures with Aluminum

### Update firmware release “12”

- Internal improvements

### Update firmware release “11”

- New synergic programs:
  - Fe SG2 0.8mm Ar+8%CO<sub>2</sub> (SHORT, PULSE)
  - Fe SG2 1.0mm Ar+8%CO<sub>2</sub> (SHORT, PULSE)
  - Fe SG2 1.2mm Ar+8%CO<sub>2</sub> (SHORT, PULSE)

### Update firmware release “10”

- New sinergic programs:
  - Rutil (E71T-1) 1.2mm Ar+18%CO<sub>2</sub> (SHORT)
  - Metal 1.2mm Ar+18%CO<sub>2</sub> (SHORT, PULSE)
  - AlSiCu (4145) 1.2mm 100%Ar (SHORT, PULSE)
  - X96 (ER120-S) 0.8mm Ar+25%CO<sub>2</sub> (SHORT, PULSE)
- Internal improvements

### Update firmware release “9”

- Internal improvements

### Update firmware release “8”

- Internal improvements



## Update firmware release "7"

- Improvements in graphical interface
- Internal improvements

## Update firmware release "6"

- TIG 3L mode updated in accordance with MIG 3L
- Improvements in graphical interface

## Update firmware release "5"

- Improvements in graphical interface

## Update firmware release "4"

- New synergic programs:
  - AISI12 (4047) 1.0mm 100% Ar (short, pulse)
  - AIMg2.7Mn (5554) 1.2mm 100% Ar (short, pulse)
- Added MMA anti-stick disable function
- Added metrics (mm) / imperial (inches) selection
- Several improvements in graphical interface

## Update firmware release "3"

- Added automatic backlight dimming
- Added support for torch cod.1245 with up/down button

## Update firmware release "2"

- Added panel lock with optional PIN code
- Added visualization of welding measures in HOLD status
- Added support for quality control and Data logger art. 408