




SCHEMA ELETTRICO PER SALDATRICE A FILO:
ART. 816 -

april '84

pos	0	1	2	3	4	5	6
A	1	●	●	●	●	●	●
B	2	●	●	●	●	●	●
R	3	●	●	●			
R	4				●	●	●
S	5			●			●
S	6		●			●	
S	7	●					